

U.S. Department
of Transportation

United States
Coast Guard



LOCAL NOTICE TO MARINERS

COASTAL WATERS FROM EASTPORT, MAINE TO SHREWSBURY, NEW JERSEY

WEEKLY SUPPLEMENT

OO INTERNET ADDRESS OO
HTTP://www.navcen.uscg.mil
OR
FTP://ftp.navcen.uscg.mil

Weekly supplemental editions contain new information only available following the monthly edition. NOTE: Chart corrections and Light List changes appear only once each. A complete listing of current discrepancies and temporary changes appear in the monthly issue, LNM 05/00. Subscription to this weekly publication is free. If you have questions about the LNM or wish to be on the mailing list, contact:

COMMANDER, FIRST COAST GUARD DISTRICT (oan)

408 Atlantic Avenue, Boston, Massachusetts 02110-3350
Telephone (Day): 1-800-848-3942. To order LNM: Ext. 8335 (After 4:30 p.m. Ext. 7722)
24 Hour FAX: (617) 223-8073
Coast Guard's Customer Infoline (8:00 a.m. - 4:00 p.m.): 1-800-368-5647.
Hearing impaired (TDD) 1-800 689-0816

All bearings are in degrees TRUE - All times are in Local Time unless otherwise noted.
NOTE: A vertical line in the RIGHT MARGIN of sections I, V, VI, VII indicates new information.

BROADCAST NOTICE TO MARINERS

The following Broadcast Notice to Mariners (BNM's) have been issued since last week:

First District	CG1- 0038	to	0048
Group Boston	BOS- 0021	to	0026
Group Long Island Sound	LIS- 0033	to	0039
Group Moriches	MOR- 0028	to	0028
Group New York	NEW- 0050	to	0059
Group Portland	POR- 0010	to	0010
Group Southwest Harbor	SWH- 0020	to	0020
Group Woods Hole	WHO- 0050	to	0055

Light List Reference: ATLANTIC COAST, VOLUME 1, COMDTPUB P16502.1, 1999 Edition

I SPECIAL NOTICES

This section contains information of Special concern to the Mariner.

NEW YORK - APPROACHES TO NEW YORK - On 5 October 1999, Ambrose Light (LLNR 720) was rebuilt using a tower with a red square on 3 red piles with a large tube in center, worded AMBROSE on the sides. Its nominal range was changed to 18NM and a height of 75 feet in (PA) 40-27.00N, 073-48.00W. This new position did not change the center of the Precautionary Area in the Approaches to the Port of New York/New Jersey which remains centered in (PA) 40-27.50N, 73-49.90W as per 33 CFR 166.151. A determination concerning any change in the size or location of the Precautionary Area will be made pending long term plans to possibly extend and deepen Ambrose Channel.
Charts: 12326, 12300 LNM 07/00 (CGD1)

II DISCREPANCIES

This section lists all discrepancies to Aids to Navigation reported and corrected since the last published list. A discrepancy is a change in the status of an aid to navigation that differs from what is published and or charted.

DISCREPANCIES (since last week)

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
4540	TWO BUSH IS LT	LT EXT	13006	SWH-0021-00	07/00
12635	DUXBURY BAY CH BY 11	BUOYSINK	13253	BOS-0022-00	07/00

13105	BARNSTABLE HBR ENT BY 5	OFF STA	13246	WHO-0053-00	07/00
17675	NARRGNSTT BAY ENT LHB NB	LT DIM	12300	WHO-0054-00	07/00
18275	PROVDNCE RIV APP CH LB 9	LT EXT	13221	WHO-0052-00	07/00
19300	ALLEN HBR BY 3	OFF STA	13223	WHO-0055-00	07/00
21080	PLUM IS LWB PI	DBN DEST	12354	LIS-0039-00	07/00
22945	CONNECTICUT RIV BY 49	OFF STA	12377	LIS-0038-00	07/00
23740	GUILFORD HBR CH BY 9	OFF STA	12372	LIS-0033-00	07/00
23745	GUILFORD HBR CH BY 10	OFF STA	12372	LIS-0034-00	07/00
23755	GUILFORD HBR CH BY 12	OFF STA	12372	LIS-0035-00	07/00
25040	NORWALK CH BY 17	OFF STA	12364	LIS-0037-00	07/00
26040	HUTCHINSON RIV BY 2	OFF STA	12364	NEW-0057-00	07/00
27475	FLUSHING BAY CH LB 4	LT EXT	12339	NEW-0058-00	07/00
27480	FLUSHING BAY CH LB 5	LT EXT	12339	NEW-0059-00	07/00

DISCREPANCIES CORRECTED

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
160	YORK HBR LBB YH	WATCHING PROPERLY	13260	POR-0010-00	07/00
255	BREAKING ROCKS BY 2	WATCHING PROPERLY	13274	BOS-0025-00	07/00
360	MARBLEHEAD LT	WATCHING PROPERLY	13006	BOS-0026-00	07/00
440	MINOTS LDG LT	RELIGHTED	13003	BOS-0004-00	03/00
11712	WEYMOUTH FORE RIV CH LB 14	WATCHING PROPERLY	13270	BOS-0023-00	07/00
11730	WEYMOUTH FORE RIV CH LB 18	WATCHING PROPERLY	13270	BOS-0024-00	07/00
12635	DUXBURY BAY CH BY 11	SEE ABOVE	13253	BOS-0019-00	06/00
16497	MEGANSETT HBR LB 6	WATCHING PROPERLY	13229	WHO-0039-00	05/00
16805	NEW BEDFORD CH LB 1	WATCHING PROPERLY	13218	WHO-0050-00	07/00
16845	NEW BEDFORD CH LB 8	WATCHING PROPERLY	13218	WHO-0051-00	07/00
17250	WAREHAM RIV BY 13	WATCHING PROPERLY	13229	WHO-0032-00	05/00
18275	PROVIDENCE RIV APP CH LB 9	RELIGHTED	13221	WHO-0052-00	07/00
19375	WARWICK COVE BY 7	RESET ON STATION	13221	WHO-0045-00	06/00
21435	PROSPECT PT LGB 23	RELIGHTED	12363	NEW-0051-00	07/00
24105	NEW HAVEN HBR CH LB 10A	WATCHING PROPERLY	12354	LIS-0036-00	07/00
28915	FLANDERS BAY BY 5	WATCHING PROPERLY	12354	MOR-0066-99	39/99
34990	GOWANUS FLATS LBB 28	WATCHING PROPERLY	12327	NEW-0050-00	07/00
35695	COMPTON CH LB 1	WATCHING PROPERLY	12324	NEW-0054-00	07/00
35765	SHREWSBURY RIV CH LB 7	WATCHING PROPERLY	12324	NEW-0055-00	07/00
37470	NEWARK BAY CH LB 14	RELIGHTED	12327	NEW-0053-00	07/00
38085	HUDSON RIV BY 58	WATCHING PROPERLY	12347	NEW-0060-00	07/00
38110	HUDSON RIV LB 59	RESET ON STATION	12347	NEW-0027-00	04/00
38285	HUDSON RIV LB 74	RESET ON STATION	12347	NEW-0028-00	03/00
38360	HUDSON RIV LB 89	RESET ON STATION	12347	NEW-0029-00	04/00
38950	HUDSON RIV LT 214	WATCHING PROPERLY	12348	NEW-0052-00	07/00

DISCREPANCIES (PRIVATE AIDS)

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
NONE THIS WEEK					

DISCREPANCIES (PRIVATE AIDS) CORRECTED

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
24633	UCONN ENVIRO MONITORING LB (SEE SECT IV)	DISCONTINUED	12300	CG1-0385-99	26/99

III TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED This section contains temporary changes and corrections to Aids to Navigation for the current week. When aids are temporarily relocated for dredging, a temporary correction shall be listed in Section IV giving the new position.

TEMPORARY CHANGES

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
2245	CLARK PT DBN 1 (SEE SECT IV)	TRUB	13318	CG1-0043-00	07/00
36165	RARITAN BAY LT 20	TRLT/DIM	12327	CG1-0045-00	07/00
36245	RARITAN BAY LT 42	TRLT/DIM	12327	CG1-0045-00	07/00
36315	RARITAN BAY LT 58	TRLT/DIM	12327	CG1-0045-00	07/00
36750	ARTHUR KILL CH LT 14	TRLT	12327	CG1-0045-00	07/00

TEMPORARY CHANGES CORRECTED

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
31560	EAST ROCKAWAY INLET B 12	RELOCATED	12350	CG1-0462-99	32/99

IV CHART CORRECTIONS

This section contains corrections to federal and private maintained Aids to Navigation, as well as NOS corrections.

This section contains corrective actions affecting chart(s). Corrections appear numerically by chart number, and pertain to that chart only. The mariner must decide which Chart(s) to correct. The following example explains the individual elements of a typical chart correction.

Chart Number ↓	Chart Edition ↓	Edition Date ↓	Last Local Notice to Mariners ↓	Horizontal Datum Reference ↓	Source of Correction ↓	Current Local Notice to Mariners ↓
12327	91 st Ed.	04/19/97	LAST LNM 26/97	NAD 83	(CG1)	27/97
(TEMP) ADD	NY-NJ-NEW YORK HARBOR - RARITAN RIVER National Dock Channel Buoy 3, green can					40°41'09.0"N 074°02'48.1"W
↑ Corrective Action	↑ Object of corrective Action					↑ Position (Degrees, minutes, seconds and tenths)

The letter (M) immediately following the chart number indicates that the correction should be applied to the Metric side of the chart only. (Temp) Indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (NM).

12327	93rd ed, 01/15/2000 LAST LNM 50/99 NAD 83 NEW EDITION NY - NJ - NEW YORK HARBOR - RARITAN BAY (New edition due to numerous notice to Mariners changes)	07/00 NOS SILVER SPRING 1:40,000/\$16.50 CGD01
(TEMP) ADD	Bergen Point Temporary Lighted Buoy 14, Fl R 4s Kill Van Kull Channel Lighted Buoy 6, Fl R 2.5s, Red	40-38-34.000N 074-08-41.300W 40-39-09.600N 074-04-49.700W
DELETE	Bergen Point Light 14	40-38-34.500N 074-08-42.600W
CHANGE	Gerristen Inlet Lighted Buoy 2 to Gerristen Inlet Buoy 2, Red nun	40-34-14.000N 073-55-03.200W
12352 (Temp) RELOCATE	27th ed.02/03/1996 LAST LNM 52/99 NAD 83 SHINNECOCK BAY TO EAST ROCKAWAY INLET CGD01 Farm Shoals Channel Lighted Buoy 2 from 40-38-03.320N 073-14-27.248W to	07/00 40-38-04.999N 073-14-28.102W
12363 DELETE	38th ed.10/18/1997 LAST LNM 47/99 NAD 83 NEW YORK - LONG ISLAND SOUND - WESTERN PART UCONN Enviromental Monitoring Lighted Buoy	07/00 CGD01 41-09-42.000N 074-10-18.000W
12364 DELETE	30th ed.02/15/1997 LAST LNM 05/00 NAD 83 NEW YORK AND CONNECTICUT - LONG ISLAND SOUND - PORT JEFFERSON UCONN Enviromental Monitoring Lighted Buoy	07/00 CGD01 41-09-42.000N 074-10-18.000W
12369 DELETE	24th ed.03/28/1998 LAST LNM 50/99 NAD 83 STRATFORD POINT TO SHERWOOD POINT UCONN Enviromental Monitoring Lighted Buoy	07/00 CGD01 41-09-42.000N 074-10-18.000W
13229 CHANGE	26th ed.11/09/1996 LAST LNM 05/00 NAD 83 SOUTH COAST OF CAPE COD AND BUZZARDS BAY bridge note: FIXED BRIDGE HOR CL 34 FT VERT CL 6FT at (PAGE C)	07/00 NOS SIVER SPRING, MD 41-33-12.800N 070-34-29.500W
RELOCATE	Buttermilk Channel Approach Buoy 4 from 41-44-12.047N 070-38-03.923W to	CGD01 41-44-12.745N 070-38-04-043W
13230 RELOCATE	44th ed.06/05/1999 LAST LNM 02/00NAD 83 MA - BUZZARDS BAY Buttermilk Channel Approach Buoy 4 from 41-44-12.047N 070-38-03.923W to	07/00 CGD01 41-44-12.745N 070-38-04-043W
13236 DELETE	29th ed.11/06/1999 LAST LNM 04/0040/99 NAD 83 CAPE COD CANAL AND APPROACHES Buttermilk Channel Approach Buoy 4A	07/00 CGD01 41-44-13.144N 070-38-03.393W
RELOCATE	Buttermilk Channel Approach Buoy 4 from 41-44-12.047N 070-38-03.923W to	41-44-12.745N 070-38-04-043W
13246 (TEMP) DELETE	35th ed.01/08/2000 LAST LNM 50/99 NAD 83 NEW EDITION MA - CAPE COD BAY (New edition due to various general changes) Cape Cod Disposal Area Lighted Buoy CC (Priv maint)	07/00 NOS SILVER SPRING 1:80,000/Loran-C/\$16.50 CGD01 41-54-57.300N 070-12-54.400W
13270 CHANGE	57th ed.11/28/1998 LAST LNM 05/00 NAD 83 BOSTON HARBOR NOS SILVER SPRING depth legend to: 4 FT BY 100 FT NOV 1997	07/00 42-17-09.900N 071-02-11.700W

13274	23rd ed.12/18/1999 LAST LNM 42/99 NAD 83 ME-NH-MA-PORTSMOUTH HARBOR TO BOSTON HARBOR (New edition due to numerous Notice to Mariners changes)	NEW EDITION	07/00 NOS SILVER SPRING 1:40,000/\$16.50 CGD01
(TEMP) CHANGE	President Roads Anchorage Lighted Buoy B to President Roads Anchorage Temporary Buoy B, Yellow can		42-20-42.938N 070-57-50-381W
13318	16th ed.03/07/1992 LAST LNM 50/99 NAD 83 FRENCHMAN BAY AND MOUNT DESERT ISLAND CGD01		07/00
RELOCATE (Temp)	Flynns Ledge Buoy 5 from 44-14-27.508N 068°17-01.479W to		44-14-27.700N 068-17-00.500W
CHANGE	Clark Point Daybeacon 1 to Clark Point Buoy 1, Green can in (PA)		44-16-41.488N 068-18-33.458W
13321	8th ed. 12/02/1989 LAST LNM 7/99 NAD 83 SOUTHWEST HARBOR AND APPROACHES		07/00 CGD01
RELOCATE (Temp)	Flynns Ledge Buoy 5 from 44-14-27.508N 068°17-01.479W to		44-14-27.700N 068-17-00.500W
CHANGE	Clark Point Daybeacon 1 to Clark Point Buoy 1, Green can in (PA)		44-16-41.488N 068-18-33.458W
13229	26th ed. 11/09/1996 LAST LNM 02/00 NAD 83 SOUTH COAST OF CAPE COD AND BUZZARDS BAY		05/00 CGD01
RELOCATE	Lewis Bay Approach Channel Buoy 15 from 41-38-20.959N 070-16-11.120W to		41-38-20.941N 070-16-11.415W

ELECTRONIC UPDATE SERVICE FOR DIGITAL CHARTS

A weekly electronic update service is now available for NOAA's digital, raster nautical charts. All Notice to Mariner corrections from USCG, NIMA and CHS are included. The service is provided via a partnership between NOAA and Maptech, Inc. Further information is available from NOAA at 301-713-2770, <http://chartmaker.ned.noaa.gov> or from Maptech at 978-933-3000, <http://www.maptech.com>.
LNM 07/00 (CGD1)

V ADVANCE NOTICES This section contains advance notice of approved projects or upcoming temporary changes such as dredging, etc. Mariners are advised to use caution while transiting these areas.

SUMMARY OF ADVANCED APPROVED PROJECTS

WATERWAY	Project Date	Ref. LNM
MA/BUTTERMILK APPROACH	29 FEB 2000	06/00
MA/MATTAPOISETT HARBOR	29 FEB 2000	06/00
MA/MARTHA'S VINEYARD	1 MAR 2000	06/00
NY/NEW YORK HARBOR	5 MAR 2000	02/00
ME/TIBBETT NARROWS TO SCHOODIC ISLAND	30 APR 2000	06/00

MA – NANTUCKET SOUND AND APPROACHES – NANTUCKET SOUND MAIN CHANNEL – The Coast Guard will be making the following change to Aids to Navigation on or about **21 February 2000** to improve the operating efficiency of the light:

Change West Chop Light (LLNR 13775) from 15 NM white and 11 NM red to 14 NM white and 11 NM red.
Chart(s) 12323, 13229, 13237 LNM 06/00 (CGD1)

NY/NJ – The Coast Guard proposes to establish temporary regulations in New York Harbor, Sandy Hook Bay, the Hudson and East Rivers, and the Kill Van Kull for OPSAIL 2000/INR 2000 activities. This action is necessary to provide for the safety of life on navigable waters during OPSAIL 2000/INR 2000. This action is intended to restrict vessel traffic in portions of New York Harbor, Sandy Hook Bay, the Hudson and East Rivers, and the Kill Van Kull. The comment period closes on **March 23, 2000**. The complete NPRM may be viewed in the Boating Info section for New York at <http://www.uscg.mil/d1/sailevents2000>. You may also obtain a copy by contacting CG Activities NY at 718-354-4197.
Chart(s) 12327, 12331, 12333, 12334, 12335, 12339, 12341, 12345, 12401, 12402. LNM 07/00 (CGD1)

NY/NJ – CAPE SABLE TO CAPE HATTERAS/WEST QUODDY HEAD TO NEW OYRK - Missile Firing exercises will be conducted surface to 90,000 within the area bounded by 40-19N 067-52W, 38-55N 065-55W, 37-42N 067-20W, 39-03N 069-15W to point of origin from 11:00 – 6:00, 21 and 22 March, 2000. Mariners are advised to use extreme caution while transiting the area.
Chart(s) 13303, 13306 LNM 07/00 (CGD1)

VI PROPOSED CHANGES

This section contains notice of non approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to: Commander, First Coast Guard District (oan), 408 Atlantic Avenue, Boston, MA 02110-3350, unless otherwise noted.

PROPOSED WATERWAY PROJECTS OPEN FOR PUBLIC COMMENT

WATERWAY	Closing	Docket No.	Ref. LNM
MA/MASS BAY- RI/NANTUCKET SHOALS	28 Feb 2000	N/A	50/99
NY/SEACOAST	29 Feb 2000	01-99-26	50/99
NY/BUTTERMILK CHANNEL	29 Feb 2000	01-00-02	03/00
ME/SOMES SOUND APPROACH	13 Mar 2000	01-00-03	06/00

ME – MONHEGAN ISLAND TO CAPE ELIZABETH – The Coast Guard is considering making the following changes to Aids to Navigation in its continuing efforts to standardize and modernize lighthouse equipment, and reduce support costs:

Change Ram Island Ledge Light (LLNR 7575) from 12NM to 9NM.
Change Seguin Light (LLNRs 35 & 5590) from 18NM to 10NM.

Interested mariners are strongly encouraged to comment on this proposal in writing, either through their organization or personally. All comments shall be carefully considered and are requested prior to **MAR 31, 2000**, to facilitate the process. In addition to the address listed, e-mail can be sent to: jmauro@d1.uscg.mil and faxes to (617) 223-8073. Refer to Docket No. 01-00-04.

Charts: 13288, 13290, 13292, 13293, 13295 LNM 07/00 (CGD1)

VII GENERAL

This section contains information of general concern to the mariner. Mariners are advised to use caution while transiting these areas.

SUMMARY OF EFFECTIVE DREDGING/CONSTRUCTION OPERATIONS

The following is a listing of marine construction and dredging projects still in effect in the First District. All mariners are advised to use caution in these areas. The LNM REF column refers to the LNM in which the article first appears and where detailed information may be obtained. The dates listed for completion are tentative. An asterisk in the left margin marks new information.

LOCATION	SUBJECT	COMPLETION DATE	LNM REF
NJ/HACKENSACK RIVER	Dredging	28 Feb 2000	03/00
RI/PROVIDENCE RIVER	Drilling holes	February 2000	45/99
NY/NJ/ARTHUR KILL	Dock Repairs	February 2000	42/99
NY/ERIE BASIN	Channel wall construction	February 2000	47/99
NY/JAMAICA BAY CROSSING	Substructure repairs	March 2000	47/99
NJ/BAYONNE	Pier construction	20 Mar 2000	42/99
NY/NJ U. S. SEACOAST	Cable laying	06 Apr 2000	06/00
MA/BOSTON HARBOR	Pier work	1 June 2000	06/00
NY/KILL VAN KULL	Dredging	15 June 2000	21/99
NY/BROOKLYN	Pier reconstruction	June 2000	26/99
NY/BROOKLYN	Dock modifications	June 2000	28/99
NY/NJ/ KILL VAN KULL	Disposal operations	September 2000	35/99
NY/BROOKLYN	Pier repairs	March 2001	39/99
NY/KILL VAN KULL	Dredging	2004	28/99
NY/BROOKHAVEN	Cable laying	Until further notice	37/99
NY/NEW YORK HARBOR	Project to measure Dissolved Oxygen	Until further notice	42/99
NY/LONG ISLAND	Cable repairs	Until further notice	44/99
MA/MARTHA'S VINEYARD	Cable retrieval/repair	Until further notice	50/99

CT – BRANFORD – Dredging is being done at the Pine Orchard Yatch Club until **1 March, 2000**. On scene is a clamshell dredge which is monitoring channels 13 and 16.

Chart(s) 12373 LNM 07/00 (CGD01)

BRIDGE SECTION

BRIDGE	TYPE	WATERWAY	NM	SUBJECT	REF/LNM
Carlton	F	Kennebec River	14.1	Bridge Construction	52-99
Summer Street Bridge	R	Reserved Channel	0.9	Bridge Construction	52-99
I-93 Main Line	F	Charles River	0.6	Bridge Construction	05-00
Brightman Street	B	Taunton River	2.1	Bridge Construction	05-00
Rt 3A	B	Weymouth Fore River	2.8	Bridge Construction	47-99
Mount Hope	F	Mount Hope Bay	0.0	Bridge Rehabilitation	47-99
Old Providence Road	F	Palmer River	0.7	Bridge Construction	05-00
I-95	F	Pequonnock River	0.0	Bridge Replacement	01-00
Tomlinson	B	Quinnipiac River	0.0	Bridge Replacement	47-99
Grand Street	B	Pequonnock River	0.9	Bridge Demolition	07-00
Route 1 (Singing)	F	Patchogue River	0.6	Bridge Rehabilitation	05-00
Goethals	F	Arthur Kill	11.5	Barge Placement	49-99
Brooklyn	F	East River	0.8	Emerg. Deck Repairs	52-99
Manhattan Bridge	F	East River	1.1	Bridge Rehabilitation	05-00
Queensboro/59 th Street	F	East River	5.5	Vert. Clear. Reduction	52-99
Robert Moses Causeway	F	Great South Bay	7.3	Bridge Rehabilitation	50 99
Third Avenue Bridge	SW	Harlem River	1.9	Bridge Closure	07-00
Macombs Dam Bridge	SW	Harlem River	3.2	Bridge Rehabilitation	04-00
George Washington	F	Hudson River	11.0	Bridge Rehabilitation	05-00
Tappan Zee	F	Hudson River	27.0	Bridge Rehabilitation	47-99
Tappan Zee	F	Hudson River	27.0	Vert. Clear. Reduction	05-00
Castleton	F	Hudson River	135.7	Vert. Clear. Reduction	51-99
Marine Parkway	VL	Jamaica Bay	3.0	Vert. Clear. Reduction	01-00
Beach Channel	SW	Jamaica Bay	6.7	Bridge Rehabilitation	50-99
Atlantic Beach	B	Reynolds Channel	0.4	Bridge Rehabilitation	50 99

Route 35	F	Navesink River	8.3	Bridge Replacement	47-99
NJ Turnpike	F	Rahway River	2.0	Bridge Painting	02-00
Route 9	F	Raritan River	2.1	Bridge Replacement	03-00

KEY: F-Fixed SW-Swing R-River C-Canal CK-Creek B-Bascule VL-Vertical Lift
Ch-Channel Hbr-Harbor Th-Thoroughfare NM-Nautical mile.

APPLICATION HAS BEEN RECEIVED FOR COAST GUARD APPROVAL OF THE FOLLOWING BRIDGE REGULATION CHANGE:

<u>BRIDGE</u>	<u>WATERWAY</u>	<u>MILE</u>	<u>RULE#</u>	<u>COMMENT PERIOD ENDS</u>	<u>REF/LNM</u>
US1 (Gillis)	Merrimac River	3.4	117.605	7 March 2000	04/00

CT - LONG ISLAND SOUND - STRATFORD POINT TO SHERWOOD POINT - BRIDGEPORT HARBOR - PEQUONNOCK RIVER - Bridge Demolition - Demolition of the Grand Street Bridge across Pequonnock River at mile 0.9 is in progress. Mariners are advised to exercise caution when transiting the area.
Chart 12369 LNM 7/00 (CGD1)

NY - JAMAICA BAY AND ROCKAWAY INLET - BEACH CHANNEL - Notice of Temporary Deviation from Regulations - Effective 0001 25 March through 1800 2 April 2000 the Beach Channel Railroad Bridge across Jamaica Bay at mile 6.7 will not open for marine traffic. The Coast Guard has issued a temporary deviation from the drawbridge operation regulations authorizing the bridge owner not to open the bridge for marine traffic during this period. This action is necessary to facilitate repairs to the operating machinery of the bridge. Mariners are advised to plan accordingly.
Chart 12350 LNM 7/00 (CGD1)

NY - NEW YORK HARBOR – EAST RIVER – HARLEM RIVER – Bridge Closure – The Third Avenue Bridge across Harlem River at mile 1.9 will not open to marine traffic until further notice due to the extensive fire damage to the bridge. Vertical clearance under the closed span is approximately 25 feet at Mean High Water. Mariners are advised to exercise caution and reduce wake when transiting the area.
Chart 12342 LNM 7/00 (CGD1)

VIII LIGHT LIST CORRECTIONS

An asterisk *, indicates the column in which a correction has been made or new information added.

(1) No.	(2) Name and location	(3) Position	(4) Characteristic	(5) Ht	(6) Rng	(7) Structure	(8) Remarks
17400	- Buoy 4A						Remove from list. * 07/00
24633	UConn Environmental Monitoring Buoy						Remove from list. * 07/00